

## PROCEDURE FOR IRRADIATOR ACCESS

- 1. All applicants shall complete the Initial Radiation Safety Training. Annual Radiation Safety Refresher Training must be current.
- 2. Principal Authorized Users (PAUs) and radiation workers, proceed to step 4 (JL Shepherd Irradiator).
- 3. If your supervisor is not authorized to use radioactive material or if you are not a PAU, a PI or a lab worker's supervisor, you must complete a one-page proposal (Research Proposal for Use of Research Irradiator). The proposal can be accessed at Augusta University's Radiation Safety website: http://www.augusta.edu/services/ehs/radsafe/documents/proposalforuseirradiator1.pdf
- 4. For access to the **JL Shepherd Irradiator** (CN Building):
  - Review and study the JL Shepherd Irradiatior training at: <a href="http://www.augusta.edu/services/ehs/radsafe/documents/jlshepherdtrainingchecklist.pdf">http://www.augusta.edu/services/ehs/radsafe/documents/jlshepherdtrainingchecklist.pdf</a>
  - Contact Fenchong (Vic) Kong at 706-446-3926 regarding an appointment to receive training instructions and a training DVD for the JL Shepherd Irradiator.
  - After hands-on training is completed, the trainer will provide a signed Training Checklist verifying that the applicant has completed the required irradiator training.
  - After the receipt of the Training Checklist, the applicant shall take the checklist to Phil Maguire in the Radiation Safety Office (CI-1029). Mr. Maguire will provide a Security T&R Form and two Reference Forms. After completing these forms, the applicant shall return the forms and Checklist to Radiation Safety.
- 5. After completing step 4, the applicant must make an appointment with Public Safety (706-721-8112) to be fingerprinted. Fingerprints will be sent to NRC/FBI for a criminal history check. The applicant's department will need to submit an IDR for \$26 to Dina Pickett at Human Resources for the applicant's NRC/FBI security review and report.
- 6. Until the applicant receives notification from the Radiation Safety Office that their clearance for unescorted access has been approved and the applicant receives instructions for the issuance of a PIN number by Public Safety for access to the irradiator, the applicant <u>must</u> be escorted into the irradiator by someone authorized unescorted access to



the irradiator room. The authorized escort <u>must remain</u> with the applicant during the entire time the applicant remains in the irradiator room.